HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 490A1520001

BRIDGE OWNER: LAUDERDALE COUNTY
ROAD NAME: SADIE HILLARD RD

CROSSING: BRANCH

LATITUDE:: N 35.91456 DEGREES LONGITUDE: W 89.43756 DEGREES

COUNTY: LAUDERDALE
ROUTE: 0A152
SPECIAL CASE: 0
COUNTY SEQUENCE: 1

LOG MILE: 0.39 YEAR BUILT: 1985

		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM OF		
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOUR		
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
Pridge hoo I	unknown foundations. Disk of acc		
		ur cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.	
		INSPECTION PROCEDURES	
What Initiat	ed the Call-out Inspection?	[] BridgeWatch Alert	
Wildt IIIItidt		TDOT District or Local Maintenance Personnel	
		THP or Local Law Enforcement Personnel	
		[] Other:	
Things to c	heck on a bridge during floods	<u>:</u>	
[] - Span	movement - horizontally as we	ell as vertically	
	•	n along curb line, both bridge rails and outer edge of bridge deck.	
	Check for plumb of piers or ben		
[] - Chec	k for embankment erosion		
[] - Chec	k for drift build-up on piers or I	pents	
[] - Chec	k pier exposure, if possible, an	d compare to previous inspection	
[] - Review the latest bridge inspection report versus current field conditions			
<u>If Closure is</u>	recommended:		
Coun temp	 Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded. 		
_		upervisor (if bridge is State maintained)	
	(2) City or County Highway	y Maintenance Official (if bridge is not State maintained)	
	(3) Tennessee Highway Pa	trol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer	
] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	State District maintenance or local highway maintenance by bridge on the selected detour route shall be checked		
	ridge can be re-opened only after a TDOT bridge inspection team checks the substructure and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 635-3500		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 635-9251		
COUNTY SHERIFF'S OFFICE	(731) 635-1311		
The report shall include the date and time o as appropriate, photographs of the bridge a	Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
COMMENTS:			
Suggested List of Equipment to conduct the Insp	ection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade	e Tape printed with the following message:		
SAFETY HAZARD KE	EP AWAY		

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

PUBLICATION DATE
17-Apr-19

A roll of Duct Tape