## **HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT**



BRIDGE ID NUMBER: 49SR0880057

BRIDGE OWNER: STATE OF TENNESSEE

ROAD NAME: S CHURCH ST CROSSING: SUMROW CREEK

COUNTY: LAUDERDALE ROUTE: SR088 SPECIAL CASE: 0 COUNTY SEQUENCE: 1

	TITUDE:: N 35.86697 DEGREE IGITUDE: W 89.39669 DEGREE		LOG MILE: <b>16.97</b> YEAR BUILT: <b>1985</b>	
		<ul> <li>TYPE OF SUPERSTRUCTURE</li> </ul>		
MAIN SPAN:	PRESTRESSED CONCRETE CONT STRINGER/MULTI-BEAM OR GIRD	INUOUS - APPR. SPAN:	NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE		
	ENTS: CONCRETE STUB ABUTMENT ON CONCRETE PILE FOUNDATION			
BENTS:				
PIERS:	CONCRETE SOLID SHAFT PIER OF	N CONCRETE PILE FOUNDATION		
		<ul> <li>SCOUR EVALUATION</li> </ul>		
event. Deter	ioration of channel protection or	riprap should be reported to TE minor repairs to the protection s	the risk of bridge failure during a flood DOT for assessment. Rip-rap protection has system are needed.	
		<ul> <li>INSPECTION PROCEDURES</li> </ul>		
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert		
		• •	al Maintenance Personnel	
		[ ] THP or Local Law Ent		
		[ ] Otner:		
Things to c	heck on a bridge during flood	le•		
_				
	movement - horizontally as v	•	o rolls and outer adap of bridge dook	
	<u>-</u>		e rails and outer edge of bridge deck.	
	Check for plumb of piers or be k for embankment erosion	ants.		
	k for drift build-up on piers o	r hants		
	• •	and compare to previous inspe	ection	
		n report versus current field c		
[ ] Novio	w the latest bridge mopeotion	Troport versus surrent neid s	onanions	
<u>If Closure is</u>	recommended:			
Coun temp	ity or City Maintenance Perso	nnel. Use Barricade Tape, trat orists to stay off of the bridge	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may	
[ ] - Conta	act: (1) District Maintenance	Supervisor (if bridge is State	maintained )	
	(2) City or County Highw	ay Maintenance Official ( if br	ridge is not State maintained )	
	(3) Tennessee Highway F	Patrol and/or local law enforce	ement Officers as appropriate	
	(4) TDOT Regional Bridg	e Engineer		
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.			

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



officials in establishing a detour route. Any brid prior to signing the detour route.	dge on the selected detour route shall be checked
[ ] - The bridge can be re-opened only after a TDOT units and they are determined to be structurally	
CONTACT PERSONNEL:	TELEPHONE NUMBER:
REGION BRIDGE ENGINEER	(731) 234-9561
DISTRICT MAINTENANCE SUPERVISOR	(901) 484-2610
TENNESSEE HIGHWAY PATROL	(901) 543-6256
as appropriate, photographs of the bridge and s scouring has occurred, the report shall also be comments:	copied to Bridge Inspection Headquarters.
Suggested List of Equipment to conduct the Inspection	<u>on:</u>
Latest Bridge Inspection Report Scour POA Report with the above Checklist	
Bridge Design Plans, if available	
Tape measure with weight	
Plumb bob	
Range Pole	
A 1000 Foot Roll of yellow Polyethylene Barricade Tap SAFETY HAZARD KEEP A	
A Barricade Tape Dispenser with serrated cutter	
A roll of Duct Tape	
Traffic Cones - Minimum of four (4)	
Traffic Safety Flares - Minimum of four (4) or set of ele	ectronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

**TDOT radio directory (State Personnel only)**