## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 500A1110001

BRIDGE OWNER: LAWRENCE COUNTY

ROAD NAME: **BRIDY RD.**CROSSING: **BRIDY CREEK** 

LATITUDE:: N 35.37035 DEGREES
LONGITUDE: W 87.32158 DEGREES

COUNTY: LAWRENCE
ROUTE: 0A111
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.90
YEAR BUILT: 1940

		TYPE OF SUPERSTRUC	TUPE -	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM OF		R. SPAN:	NOT APPLICABLE
WAIN OF AIN.	OTELL - OTKINGLIVMOLTI-BLAIM OF	OIRDER ATT	IX. OI AIV.	NOT ALL EIGABLE
		TYPE OF SUBSTRUCT	rure <del>-</del>	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTMEN	T ON CONCRETE SPRE	AD FOOTIN	NG FOUNDATION
BENTS:	NOT APPLICABLE			
PIERS:	NOT APPLICABLE			
		SCOUR EVALUATION	о <b>н</b> —	
Bridge has u	ınknown foundations. Risk of sco	ır cannot be determir	ned. The I	bridge shall be monitored for distress
	icant flood events. Monitor bridge			
		INSPECTION PROCED	IIDES —	
What Initiat	ad the Call out Inspection?			
What Initiated the Call-out Inspection?		[ ] BridgeWatch		l Maintananaa Paraannal
				Il Maintenance Personnel
				orcement Personnel
		[ ] Other:		
Things to c	heck on a bridge during floods			
_				
	movement - horizontally as we	•		
	·		tn briage	e rails and outer edge of bridge deck.
	Check for plumb of piers or ben	S.		
	k for embankment erosion			
	k for drift build-up on piers or l		:	
	k pier exposure, if possible, an	•	-	
[ ] - Revie	ew the latest bridge inspection	eport versus currer	nt fleid co	onditions
If Closure is	recommended:			
		occ road until bride	ao io coo	ured and properly alocad by District
<ul> <li>Stay at bridge with vehicle pulled across road until bridge is second county or City Maintenance Personnel. Use Barricade Tape, traff</li> </ul>				
				until such time as the bridge may
be pr	operly closed and barricaded.			
[ ] - Conta	act: (1) District Maintenance S	pervisor ( if bridge	is State	maintained )
	(2) City or County Highway	Maintenance Offici	ial (if bri	idge is not State maintained )
	(3) Tennessee Highway Pa	rol and/or local law	enforce	ment Officers as appropriate
	(4) TDOT Regional Bridge	Engineer		
	- The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.			

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[ ] - The bridge inspection team will work with State District maintenance or local highway maintenance



	fficials in establishing a detour route. Any br	idge on the selected detour route shall be checked			
		idge can be re-opened only after a TDOT bridge inspection team checks the substructure and they are determined to be structurally stable.			
<u>C</u>	ONTACT PERSONNEL:	TELEPHONE NUMBER:			
С	OUNTY MAYOR'S OFFICE	(931) 762-7700			
н	WY. CHIEF ADMINISTRATOR'S OFFICE	(931) 762-4272			
С	OUNTY SHERIFF'S OFFICE	(931) 762-3626			
TI as so	he report shall include the date and time of th				
Sugges	ted List of Equipment to conduct the Inspect	ion:			
Latest E	Bridge Inspection Report				
	OA Report with the above Checklist				
_	Design Plans, if available				
•	easure with weight				
Plumb I					
Range I					
A 1000	Foot Roll of yellow Polyethylene Barricade Ta				
	SAFETY HAZARD KEEP	AWAY			

TDOT radio directory (State Personnel only)

Traffic Cones - Minimum of four (4)

A Barricade Tape Dispenser with serrated cutter

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

A roll of Duct Tape