HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



COUNTY: LINCOLN

BRIDGE ID NUMBER: 520A1760001

BRIDGE OWNER: LINCOLN COUNTY

ROAD NAME: STEELMAN RD

CROSSING: EAST FORK MULBERRY CREEK
LATITUDE:: N 35.21897 DEGREES
LONGITUDE: W 86.42773 DEGREES

ROUTE: 0A001
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.28
YEAR BUILT: 1947

		TYPE OF SUPERSTRUCTURE =	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM OF		NOT APPLICABLE
		TYPE OF SUBSTRUCTURE =	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME		NG FOUNDATION
BENTS:	NOT APPLICABLE	TO THE STATE OF TH	
PIERS:	CONCRETE SOLID SHAFT PIER ON	CONCRETE SPREAD FOOTING FO	UNDATION
		SCOUR EVALUATION -	
	unknown foundations. Risk of sco icant flood events. Monitor bridge		bridge shall be monitored for distress termeasures.
		INSPECTION PROCEDURES =	
What Initiat	ed the Call-out Inspection?	[] BridgeWatch Alert	
		[] TDOT District or Loca	al Maintenance Personnel
		[] THP or Local Law Enf	forcement Personnel
		[] Other:	
Things to c	<u>heck on a bridge during floods</u>	<u>:</u>	
[] - Span	movement - horizontally as we	ell as vertically	
1. 0	Check displacement / deflection	n along curb line, both bridge	e rails and outer edge of bridge deck.
2. 0	Check for plumb of piers or ber	nts.	
[] - Chec	k for embankment erosion		
[] - Chec	k for drift build-up on piers or l	pents	
[] - Chec	k pier exposure, if possible, an	d compare to previous inspe	ection
[] - Revie	ew the latest bridge inspection	report versus current field c	onditions
	recommended:		
Coun temp	tay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, ounty or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as emporary measures to warn motorists to stay off of the bridge until such time as the bridge may e properly closed and barricaded.		
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State	maintained)
	(2) City or County Highway	y Maintenance Official (if br	idge is not State maintained)
	(3) Tennessee Highway Pa	trol and/or local law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	
	e Bridge should remain closed until the water recedes and a daylight visual inspection is made a TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



	icials in establishing a detour route. Any brid for to signing the detour route.	lge on the selected detour route shall be checked	
	dge can be re-opened only after a TDOT bridge inspection team checks the substructure nd they are determined to be structurally stable.		
CO	NTACT PERSONNEL:	TELEPHONE NUMBER:	
со	UNTY MAYOR'S OFFICE	(931) 433-3045	
HW	Y. CHIEF ADMINISTRATOR'S OFFICE	(931) 433-2585	
СО	UNTY SHERIFF'S OFFICE	(931) 433-3111	
as a	e report shall include the date and time of the appropriate, photographs of the bridge and souring has occurred, the report shall also be o	copied to Bridge Inspection Headquarters.	
Suggeste	ed List of Equipment to conduct the Inspection	on:	
Latest Br	idge Inspection Report		
	OA Report with the above Checklist		
_	esign Plans, if available		
•	asure with weight		
Plumb bo			
Range Po			
A 1000 F	oot Roll of yellow Polyethylene Barricade Tap		
	SAFETY HAZARD KEEP A	NWAY	

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)