Rev. 07-24-15		WAY BRIDGE SCOUR I OF ACTION REPORT	TN TDOT Department of Transportation
BRIDGE ( ROAI CR( LAT	IUMBER: 53023560003 OWNER: LOUDON COUNTY D NAME: RIVER RD OSSING: SWEETWATER CREEK TITUDE:: N 35.73820 DEGREES GITUDE: W 84.37388 DEGREES		COUNTY: LOUDON ROUTE: 02356 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 1.15 YEAR BUILT: 1970
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	PRESTRESSED CONCRETE - BOX E GIRDERS - MULTIPLE		NOT APPLICABLE
	CONCRETE STUB ABUTMENT ON L		
BENTS:	CONCRETE COLUMN TWO POST B		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
	nknown foundations. Risk of sco cant flood events. Monitor bridge	in lieu of installing scour count	oridge shall be monitored for distress termeasures.
What Initiate	ed the Call-out Inspection?	INSPECTION PROCEDURES – [ ] BridgeWatch Alert [ ] TDOT District or Loca [ ] THP or Local Law Enfo	l Maintenance Personnel orcement Personnel

## Things to check on a bridge during floods:

- [] Span movement horizontally as well as vertically
  - 1. Check displacement / deflection along curb line, both bridge rails and outer edge of bridge deck.

[] Other:

- 2. Check for plumb of piers or bents.
- [] Check for embankment erosion
- [] Check for drift build-up on piers or bents
- [] Check pier exposure, if possible, and compare to previous inspection
- [ ] Review the latest bridge inspection report versus current field conditions

## If Closure is recommended:

- [] Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded.
- [ ] Contact: (1) District Maintenance Supervisor ( if bridge is State maintained )
  - (2) City or County Highway Maintenance Official (if bridge is not State maintained)
  - (3) Tennessee Highway Patrol and/or local law enforcement Officers as appropriate
  - (4) TDOT Regional Bridge Engineer
- [] The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.

P	UB	LICA	N D	ATE	

07-Nov-24



- [] The bridge inspection team will work with State District maintenance or local highway maintenance officials in establishing a detour route. Any bridge on the selected detour route shall be checked prior to signing the detour route.
- [] The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.

CONTACT PERSONNEL:	TELEPHONE NUMBER:
COUNTY MAYOR'S OFFICE	(865) 458-4664
HWY. CHIEF ADMINISTRATOR'S OFFICE	(865) 458-6940
COUNTY SHERIFF'S OFFICE	(865) 986-4823

[ ] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.

COMMENTS: \_\_\_\_\_

Suggested List of Equipment to conduct the Inspection:

Latest Bridge Inspection Report

Scour POA Report with the above Checklist

Bridge Design Plans, if available

Tape measure with weight

Plumb bob

**Range Pole** 

A 1000 Foot Roll of yellow Polyethylene Barricade Tape printed with the following message:

## SAFETY HAZARD KEEP AWAY

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)

PUBLICATION DATE