## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 540A0560001

BRIDGE OWNER: McMINN COUNTY

ROAD NAME: CHICKEN HOUSE RD

CROSSING: BIG SEWEE CREEK

LATITUDE:: N 35.63247 DEGREES

COUNTY: McMINN
ROUTE: 0A056
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.75
YEAR BUILT: 1970

LON	NGITUDE: W 84.60929 DEGREES	YEAR BUILT: 1970			
MAIN SPAN:	PRESTRESSED CONCRETE - BOX GIRDERS - MULTIPLE	TYPE OF SUPERSTRUCTURE  BEAM OR APPR. SPAN: NOT APPLICABLE			
		TYPE OF SUBSTRUCTURE			
ABUTMENTS:	TMENTS: CONCRETE FULL HEIGHT ABUTMENT ON CONCRETE SPREAD FOOTING FOUNDATION				
BENTS:	NOT APPLICABLE				
PIERS:	NOT APPLICABLE				
		SCOUR EVALUATION			
		our cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.			
		INSPECTION PROCEDURES			
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert			
		[ ] TDOT District or Local Maintenance Personnel			
		[ ] THP or Local Law Enforcement Personnel			
		[ ] Other:			
[ ] - Span 1. C 2. C [ ] - Chec [ ] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a	ell as vertically n along curb line, both bridge rails and outer edge of bridge deck. nts.			
<u>If Closure is</u>	recommended:				
Coun temp	y at bridge with vehicle pulled across road until bridge is secured and properly closed by District, unty or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as apporary measures to warn motorists to stay off of the bridge until such time as the bridge may properly closed and barricaded.				
[ ] - Conta	act: (1) District Maintenance S	upervisor ( if bridge is State maintained )			
	(2) City or County Highwa	y Maintenance Official ( if bridge is not State maintained )			
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate			
	(4) TDOT Regional Bridge	Engineer			
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.				

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	hing a detour route. Any bri	te District maintenance or local highway maintenance idge on the selected detour route shall be checked	
	<ul> <li>The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.</li> </ul>		
CONTACT PERSONNEI	<u>.:</u>	TELEPHONE NUMBER:	
COUNTY MAYOR'S OF	FICE	(423) 745-7634	
HWY. CHIEF ADMINIST	RATOR'S OFFICE	(423) 745-1820	
COUNTY SHERIFF'S O	FICE	(423) 745-5620	
The report shall inc	<ul> <li>Summarize and submit findings from the inspection to BridgeWatch scour monitoring system.</li> <li>The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.</li> </ul>		
Suggested List of Equipr	nent to conduct the Inspect	ion:	
Latest Bridge Inspection	Report		
Scour POA Report with the	ne above Checklist		
Bridge Design Plans, if a	vailable vailable		
Tape measure with weigh	ıt		
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow	• •	ape printed with the following message:	
	SAFETY HAZARD KEEP	AWAY	

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24