HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 55016570003

BRIDGE OWNER: McNAIRY COUNTY

ROAD NAME: CYPRESS RD

CROSSING: CYPRESS CREEK

LATITUDE:: N 35.02719 DEGREES
LONGITUDE: W 88.70764 DEGREES

COUNTY: McNAIRY
ROUTE: 01657
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 4.14
YEAR BUILT: 1988

LON	NGITUDE: W 88.70764 DEGREES	YEAR BUILT: 1988	
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	PRESTRESSED CONCRETE - BOX GIRDERS - SINGLE OR SPREAD	BEAM OR APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	UTMENTS: CONCRETE STUB ABUTMENT ON CONCRETE PILE FOUNDATION		
BENTS:	NOT APPLICABLE		
PIERS:	CONCRETE HAMMERHEAD PIER O	N CONCRETE PILE FOUNDATION	
		SCOUR EVALUATION	
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.	
		INSPECTION PROCEDURES -	
What Initiated the Call-out Inspectio		[] BridgeWatch Alert	
		[] TDOT District or Local Maintenance Personnel	
		[] THP or Local Law Enforcement Personnel	
		[] Other:	
1. C 2. C [] - Chec [] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a	n along curb line, both bridge rails and outer edge of bridge deck. nts.	
<u>If Closure is</u>	recommended:		
Coun temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, anel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may	
[] - Conta	act: (1) District Maintenance S	supervisor (if bridge is State maintained)	
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)	
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer	
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



	ficials in establishing a detour route. Any b ior to signing the detour route.	ridge on the selected detour route shall be checked		
		ean be re-opened only after a TDOT bridge inspection team checks the substructure ey are determined to be structurally stable.		
<u>co</u>	NTACT PERSONNEL:	TELEPHONE NUMBER:		
co	DUNTY MAYOR'S OFFICE	(731) 645-3472		
ни	VY. CHIEF ADMINISTRATOR'S OFFICE	(731) 645-3651		
co	DUNTY SHERIFF'S OFFICE	(731) 645-1000		
as sco	appropriate, photographs of the bridge and	the inspection, a brief summary of findings and, distream channel measurements. If significant be copied to Bridge Inspection Headquarters.		
Suggest	ed List of Equipment to conduct the Inspec	etion:		
Latest B	ridge Inspection Report			
	OA Report with the above Checklist			
_	esign Plans, if available			
•	asure with weight			
Plumb be				
Range P				
A 1000 F	oot Roll of yellow Polyethylene Barricade 1			
	SAFETY HAZARD KEE	PAWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24