HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



COUNTY: McNAIRY

BRIDGE ID NUMBER: 55SR0220011

BRIDGE OWNER: STATE OF TENNESSEE

ROAD NAME: SR22

CROSSING: SAM BISHOP DITCH
LATITUDE:: N 35.35906 DEGREES
LONGITUDE: W 88.36689 DEGREES

ROUTE: SR022
SPECIAL CASE: 0
COUNTY SEQUENCE: 2
LOG MILE: 8.87
VEAR BUILT: 1958

LON	NGHODE. W 66.30069 DEGREES	TEAN BOILT. 1930	
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE STUB ABUTMENT ON C	CONCRETE PILE FOUNDATION	
BENTS: CONCRETE PILE BENT ON PILE FO		UNDATION	
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
Bridge is see	our critical: bridge foundations de	etermined to be unstable for calculated scour conditions. Rip-rap protection	
	stalled and is in good condition.	stermined to be unstable for calculated scoul conditions. Typ-rap protection	
		INSPECTION PROCEDURES ————————————————————————————————————	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
		[] TDOT District or Local Maintenance Personnel	
		[] THP or Local Law Enforcement Personnel	
		[] Other:	
Things to c	heck on a bridge during floods	<u>s:</u>	
[] - Span	movement - horizontally as w	ell as vertically	
1. 0	Check displacement / deflectio	n along curb line, both bridge rails and outer edge of bridge deck.	
2. 0	Check for plumb of piers or be	nts.	
[] - Chec	k for embankment erosion		
[] - Chec	k for drift build-up on piers or	bents	
[] - Chec	k pier exposure, if possible, ar	nd compare to previous inspection	
[] - Revie	w the latest bridge inspection	report versus current field conditions	
	recommended:		
Coun temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may	
[] - Conta	act: (1) District Maintenance S	supervisor (if bridge is State maintained)	
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)	
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer	
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



officials in establishing a detour route. Any brid	ge on the selected detour route shall be checked	
[] - The bridge can be re-opened only after a TDOT bridge inspection team checks the substructural units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
REGION BRIDGE ENGINEER	(731) 234-9561	
DISTRICT MAINTENANCE SUPERVISOR	(731) 694-6673	
TENNESSEE HIGHWAY PATROL	(731) 423-6635	
The report shall include the date and time of the as appropriate, photographs of the bridge and st scouring has occurred, the report shall also be c	tream channel measurements. If significant copied to Bridge Inspection Headquarters.	
Suggested List of Equipment to conduct the Inspection	<u>n:</u>	
Latest Bridge Inspection Report		
Scour POA Report with the above Checklist		
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole		
A 1000 Foot Roll of yellow Polyethylene Barricade Tap		
SAFETY HAZARD KEEP A	WAY	

TDOT radio directory (State Personnel only)

Traffic Cones - Minimum of four (4)

A Barricade Tape Dispenser with serrated cutter

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

A roll of Duct Tape