## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



COUNTY: MADISON

BRIDGE ID NUMBER: 57\$81880027

BRIDGE OWNER: STATE OF TENNESSEE ROAD NAME: BEECH BLUFF RD

CROSSING: N. FK. FORKED DEER RIVER
LATITUDE:: N 35.59258 DEGREES
LONGITUDE: W 88.63742 DEGREES

ROUTE: SR198
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 11.69

LOI	NGHODE. W 66.03742 DEGREES	•	TEAN BOILT. 1901	
		TYPE OF SUPERSTRUCTURE		
MAIN SPAN:	PRESTRESSED CONCRETE CONTI STRINGER/MULTI-BEAM OR GIRDE		NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE		
ABUTMENTS:	CONCRETE STUB ABUTMENT ON O	RETE STUB ABUTMENT ON CONCRETE PILE FOUNDATION		
BENTS:	NTS: NOT APPLICABLE			
PIERS:	CONCRETE HAMMERHEAD PIER O	N CONCRETE PILE FOUNDATION		
		SCOUR EVALUATION		
	our critical; bridge foundations de sures are installed but they are n		culated scour conditions. No scour	
		INSPECTION PROCEDURES =		
What Initiated the Call-out Inspection		[ ] BridgeWatch Alert		
		[ ] TDOT District or Loca	al Maintenance Personnel	
		[ ] THP or Local Law En	forcement Personnel	
		[ ] Other:		
[ ] - Span 1. 0 2. 0 [ ] - Chec [ ] - Chec	heck on a bridge during floods movement - horizontally as w Check displacement / deflectio Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar ew the latest bridge inspection	ell as vertically n along curb line, both bridgents. bents nd compare to previous inspe		
[ ] - Stay Cour temp	nty or City Maintenance Person orary measures to warn motor	nnel. Use Barricade Tape, trat rists to stay off of the bridge	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may	
be properly closed and barricaded.  [ ] - Contact: (1) District Maintenance Supervisor ( if bridge is State maintained )				
L J COIN	` '	, , ,	ridge is not State maintained)	
	``	· ·	ement Officers as appropriate	
	(4) TDOT Regional Bridge		Silvere de appropriate	
[ ] - The F	` '	•	daylight visual inspection is made	
	a TDOT bridge inspection team.			

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	te District maintenance or local highway maintenance idge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
REGION BRIDGE ENGINEER	(731) 234-9561		
DISTRICT MAINTENANCE SUPERVISOR	(731) 694-6673		
TENNESSEE HIGHWAY PATROL	(731) 423-6635		
<ul> <li>Summarize and submit findings from the inspe The report shall include the date and time of th as appropriate, photographs of the bridge and scouring has occurred, the report shall also be</li> </ul>	e inspection, a brief summary of findings and, stream channel measurements. If significant		
COMMENTS:			
Suggested List of Equipment to conduct the Inspect	ion:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Ta			
SAFETY HAZARD KEEP	AWAY		

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24