HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 790A7280003

BRIDGE OWNER: CITY OF COLLIERVILLE

ROAD NAME: FRANK RD CROSSING: BRANCH

LATITUDE:: N 35.06911 DEGREES LONGITUDE: W 89.69050 DEGREES

COUNTY: SHELBY
ROUTE: 04040
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 2.40

LON	IGITUDE: W 89.69050 DEGREES	YEAR BUILT: 1970
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE STUB ABUTMENT ON C	ONCRETE PILE FOUNDATION
BENTS:	CONCRETE COLUMN FOUR OR MO	RE POST BENT ON CONCRETE PILE FOUNDATION
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
		our cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
[] - Span 1. C 2. C [] - Chec [] - Chec	Check for plumb of piers or ber k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, an	ell as vertically n along curb line, both bridge rails and outer edge of bridge deck. nts.
<u>If Closure is</u>	recommended:	
Coun temp	ty or City Maintenance Person	cross road until bridge is secured and properly closed by District, anel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State maintained)
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	Bridge should remain closed u FDOT bridge inspection team.	ntil the water recedes and a daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	am will work with State District maintenance or local highway maintenance detour route. Any bridge on the selected detour route shall be checked ir route.		
[] - The bridge can be re-ope units and they are determ	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
CITY MAYOR'S OFFICE	(901) 457-2200		
CITY ENGINEER'S OFFICE	(901) 457-2310		
POLICE OFFICE	(901) 457-2513		
The report shall include the as appropriate, photograp	- Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
COMMENTS:			
Suggested List of Equipment to Latest Bridge Inspection Report	·		
Scour POA Report with the abo			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
•	ethylene Barricade Tape printed with the following message:		
QA.	FETY HAZARD KEEP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)