HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 79SR0010015

BRIDGE OWNER: STATE OF TENNESSEE

ROAD NAME: **SUMMER AVE** CROSSING: **WOLF RIVER**

LATITUDE:: N 35.15825 DEGREES LONGITUDE: W 89.88278 DEGREES

COUNTY: SHELBY
ROUTE: SR001
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 12.52

LON	NGHODE: W 89.88278 DEGREES	YEAR BUILT: 1926
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN: CONCRETE - TEE BEAM
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE STUB ABUTMENT ON (CONCRETE PILE FOUNDATION
BENTS:	CONCRETE PILE BENT ON PILE FO	DUNDATION
PIERS:	CONCRETE COLUMNS WITH SOLI	WEB WALL (DUMB BELL) ON TIMBER PILE FOUNDATION
		SCOUR EVALUATION
Bridge has I	unknown foundations. Bisk of sec	
during signif		our cannot be determined. The bridge shall be monitored for distress ction has been installed and is in fair condition. Some minor repairs to the
		INSPECTION PROCEDURES -
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
	·	[] TDOT District or Local Maintenance Personnel
		THP or Local Law Enforcement Personnel
		[] Other:
1. 0 2. 0 [] - Chec [] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a	n along curb line, both bridge rails and outer edge of bridge deck. nts.
If Closure is	recommended:	
Cour temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
		Supervisor (if bridge is State maintained)
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer Engineer
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



officials in establishing a detour route. Any bridg prior to signing the detour route.	ge on the selected detour route shall be checked		
[] - The bridge can be re-opened only after a TDOT b units and they are determined to be structurally s	can be re-opened only after a TDOT bridge inspection team checks the substructure		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
REGION BRIDGE ENGINEER	(731) 234-9561		
DISTRICT MAINTENANCE SUPERVISOR	(901) 484-2610		
TENNESSEE HIGHWAY PATROL	(901) 543-6256		
The report shall include the date and time of the i as appropriate, photographs of the bridge and str scouring has occurred, the report shall also be co	ream channel measurements. If significant opied to Bridge Inspection Headquarters.		
Suggested List of Equipment to conduct the Inspection	<u>ı:</u>		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Tape			
SAFETY HAZARD KEEP AV	NAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)