HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 840B0780001
BRIDGE OWNER: TIPTON COUNTY
ROAD NAME: MOCKINGBIRD DRIVE

CROSSING: BRANCH

LATITUDE:: N 35.39583 DEGREES LONGITUDE: W 89.69537 DEGREES

COUNTY: TIPTON
ROUTE: 0B078
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.32

LON	IGITUDE: W 89.69537 DEGREES		YEAR BUILT: 1984	
MAIN SPAN:	STEEL - CULVERT (INCLUDES FRAM	TYPE OF SUPERSTRUCTURE = IE CULVERTS) APPR. SPAN:	NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE =		
ABUTMENTS:	OTHER (CMP, CP, MA, ETC.) ON UNI			
BENTS:	NOT APPLICABLE			
PIERS:	NOT APPLICABLE			
		COOLID EVALUATION		
D.1. I		SCOUR EVALUATION =		
	inknown foundations. Risk of scolicant flood events. Monitor bridge		bridge shall be monitored for distress termeasures.	
		INSPECTION PROCEDURES =		
What Initiated the Call-out Inspection?		[] BridgeWatch Alert		
		[] TDOT District or Loca	al Maintenance Personnel	
		[] THP or Local Law Ent	forcement Personnel	
		[] Other:		
Things to c	<u>heck on a bridge during floods</u>	<u> </u>		
1. 0	movement - horizontally as we Check displacement / deflection Check for plumb of piers or ben	along curb line, both bridge	e rails and outer edge of bridge deck.	
	k for embankment erosion	15.		
	k for drift build-up on piers or b	nants		
	k pier exposure, if possible, an		ection	
	ew the latest bridge inspection			
[] - Revie	w the latest bridge inspection	report versus current neid c	onditions	
If Closure is	recommended:			
Coun temp	ity or City Maintenance Person	nel. Use Barricade Tape, traf	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may	
[] - Conta	act: (1) District Maintenance Su	pervisor (if bridge is State	maintained)	
	(2) City or County Highway	Maintenance Official (if br	idge is not State maintained)	
	(3) Tennessee Highway Pa	trol and/or local law enforce	ement Officers as appropriate	
	(4) TDOT Regional Bridge			
	- The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.			

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	detour route. Any bridge on	ct maintenance or local highway maintenance the selected detour route shall be checked			
[] - The bridge can be re-oper units and they are determ	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.				
CONTACT PERSONNEL:		TELEPHONE NUMBER:			
COUNTY MAYOR'S OFFICE		(901) 476-0200			
HWY. CHIEF ADMINISTRATOR'S	3 OFFICE	(901) 837-5900			
COUNTY SHERIFF'S OFFICE		(901) 475-3300			
The report shall include th as appropriate, photograp	 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 				
COMMENTS:					
Suggested List of Equipment to	•				
Latest Bridge Inspection Report Scour POA Report with the above					
Bridge Design Plans, if available					
Tape measure with weight	•				
Plumb bob					
Range Pole					
A 1000 Foot Roll of yellow Polye	ethylene Barricade Tape prin	ed with the following message:			
SAF	EETY HAZARD KEED AWAY				

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24