HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 05024060001

BRIDGE OWNER: TOWN OF LOUISVILLE
ROAD NAME: MISER STATION RD
CROSSING: FORT LOUDON LAKE
LATITUDE:: N 35.80795 DEGREES
LONGITUDE: W 84.02743 DEGREES

COUNTY: BLOUNT
ROUTE: 02406
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 3.29
YEAR BUILT: 1942

201	101105E. 11 04.02140	TE/III DOILL. 1042
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	CONCRETE - GIRDER AND FLOOR	BEAM SYSTEM APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
	10171111071511	
		SCOUR EVALUATION
		our cannot be determined. The bridge shall be monitored for distress le in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiat	ed the Call-out Inspection?	[] BridgeWatch Alert
	·	[] TDOT District or Local Maintenance Personnel
		THP or Local Law Enforcement Personnel
		[] Other:
Things to c	heck on a bridge during flood	<u>s:</u>
[] - Span	movement - horizontally as w	vell as vertically
	•	on along curb line, both bridge rails and outer edge of bridge deck.
2. 0	Check for plumb of piers or be	ents.
[] - Chec	k for embankment erosion	
[] - Chec	k for drift build-up on piers or	bents
[] - Chec	k pier exposure, if possible, a	nd compare to previous inspection
[] - Revie	w the latest bridge inspection	report versus current field conditions
<u>f Closure is</u>	recommended:	
Coun temp	nty or City Maintenance Person	ncross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may.
[] - Contact: (1) District Maintena		Supervisor (if bridge is State maintained)
	(2) City or County Highwa	ay Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	Bridge should remain closed u TDOT bridge inspection team.	Intil the water recedes and a daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



 The bridge inspection team will work with State District maintenance or local highway maintenance officials in establishing a detour route. Any bridge on the selected detour route shall be checked prior to signing the detour route. 			
[] - The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.			
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
CITY MAYOR'S OFFICE	(865) 681-1983		
	he inspection, a brief summary of findings and, d stream channel measurements. If significant		
COMMENTS:			
Suggested List of Equipment to conduct the Inspec	etion:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade 1			
SAFETY HAZARD KEE	PAWAY		
A Barricade Tape Dispenser with serrated cutter			
A roll of Duct Tape			
Traffic Cones - Minimum of four (4)			
Traffic Safety Flares - Minimum of four (4) or set of	_		
TDOT two-way radio (State Personnel only) and/or cellular telephone			

TDOT radio directory (State Personnel only)