## **HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT**



BRIDGE ID NUMBER: 43\$62210007

BRIDGE OWNER: HUMPHREYS COUNTY ROAD NAME: N CLYDEDON RD CROSSING: SPRING CREEK

COUNTY: HUMPHREYS ROUTE: 00910 SPECIAL CASE: 0 COUNTY SEQUENCE: 1

	.TITUDE:: N 36.16142 DEGREES NGITUDE: W 87.83052 DEGREES			LOG MILE: <b>27.65</b> YEAR BUILT: <b>1975</b>
		TYPE OF SUPER	RSTRUCTURE -	
MAIN SPAN:	CONCRETE CONTINUOUS - CULVE FRAME CULVERTS)		APPR. SPAN:	CONCRETE - CULVERT (INCLUDES FRAME CULVERTS)
		TYPE OF SUB	STRUCTURE -	
ABUTMENTS:	CONCRETE BOX TYPE ON CONCRE	ETE SPREAD FOO	TING FOUNDATIO	N
BENTS:	NOT APPLICABLE			
PIERS:	PIER WALL FOR CONCRETE BOX (	ON CONCRETE SP	READ FOOTING F	OUNDATION
		SCOUR EVA	ALUATION -	
is required to		s. Rip-rap prote	ction has been i	red at bridge foundations. Immediate action nstalled but is in poor condition. Significant
		- INSPECTION PI		
What Initiated the Call-out Inspection?		[ ] Bridge\		
				Il Maintenance Personnel
				orcement Personnel
		[ ] Other.		
Things to c	heck on a bridge during floods	s:		
_			,	
	movement - horizontally as w Sheck displacement / deflection	•		e rails and outer edge of bridge deck.
	Check for plumb of piers or be	_	ne, both bridge	rans and outer eage or bridge deor.
	k for embankment erosion			
	k for drift build-up on piers or	bents		
	k pier exposure, if possible, ar		previous inspe	ection
	ew the latest bridge inspection	-	•	
		-		
<u>If Closure is</u>	recommended:			
Coun temp	ity or City Maintenance Persor	nnel. Use Barrio rists to stay off	cade Tape, traf	ured and properly closed by District, fic cones and/or traffic flares as until such time as the bridge may
[ ] - Conta	act: (1) District Maintenance S	Supervisor (if I	bridge is State	maintained )
	(2) City or County Highwa	y Maintenance	Official (if br	idge is not State maintained )
	(3) Tennessee Highway Pa	atrol and/or loc	cal law enforce	ment Officers as appropriate
	(4) TDOT Regional Bridge	Engineer		
	he Bridge should remain closed until the water recedes and a daylight visual inspection is made y a TDOT bridge inspection team.			

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



officials in establishing a detour route. Any bridg prior to signing the detour route.	ge on the selected detour route shall be checked
[ ] - The bridge can be re-opened only after a TDOT be units and they are determined to be structurally struc	
CONTACT PERSONNEL:	TELEPHONE NUMBER:
COUNTY MAYOR'S OFFICE	(931) 296-7795
HWY. CHIEF ADMINISTRATOR'S OFFICE	(931) 296-2121
COUNTY SHERIFF'S OFFICE	(931) 296-2301
<ul> <li>Summarize and submit findings from the inspection         The report shall include the date and time of the inspection as appropriate, photographs of the bridge and structured in the second in the se</li></ul>	inspection, a brief summary of findings and, ream channel measurements. If significant
COMMENTS:	
<u> </u>	
·	
Suggested List of Equipment to conduct the Inspection	<u>n:</u>
Latest Bridge Inspection Report	
Scour POA Report with the above Checklist	
Bridge Design Plans, if available	
Tape measure with weight	
Plumb bob	
Range Pole	
A 1000 Foot Roll of yellow Polyethylene Barricade Tape	e printed with the following message:
SAFETY HAZARD KEEP AV	WAY
A Barricade Tape Dispenser with serrated cutter	
A roll of Duct Tape	
Traffic Cones - Minimum of four (4)	

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

**TDOT radio directory (State Personnel only)**